

Serial No.: 10/798,020
Art Unit: 2833

Amendments to the Specification:

Please replace the first paragraph on page 2 of the specification with the following amended paragraph.

document US 2002/0111,068~~-A-0-111-068~~. However, this connector is subject to the risk of the metal bracket touching conductors of adjacent circuit boards when one circuit boards is being inserted between adjacent circuit boards, thus producing a short-circuit. Furthermore, the connector is not very robust and is difficult to assemble.

Serial No.: 10/798,020
Art Unit: 2833

Amendments to the Drawings

The attached eight sheets of drawings include replacement sheets for Figs. 1 through 21. The eight sheets replace the original eight sheets of drawings including Figs. 1 through 21.

Attachments: Replacement Sheets (8)